


Vehicle Restraint System Field Repair Manual



November 2011 Revision A

The information contained within this document is the sole property of Holland L.P. and is unauthorized for reproduction without expressed, written permission. If you have received this document in error, please return to:


Holland L.P. 1000 Holland Drive Crete, IL 60417



Table of Contents

Retractor Replacement, Part No. 74345	2	
Left Pedal Replacement, Part No. 74347	5	
Right Pedal Replacement, Part No. 74348	7	
Top Cover Replacement, Part No. 74350	9	
Tire Grip Replacement, Part No. 74353	13	

Required Tools






Retractor Replacement

Part No. 74345

Retractor Kit Bill of Material

Description	Quantity	
Retractor assembly, Part No. 7052-10	1	
M6 X 0.8-12 Button head screw	8	
M6 X 0.8-20 SOC Flat head screw	2	








- Any part of the strap is torn
- Hook becomes severely deformed
- Retractor locks up and will no longer retract or extend
- Plastic coating on hook is peeling off




Retractor Replacement Disassembly





Retractor Replacement Reassembly





Left Pedal Replacement

Part No. 74347

Left Pedal Kit Bill of Material


Description	Quantity	
Left pedal assembly Lock pedal, Part No. 7052-16 (Qty: 1) Pedal cover red, Part No. 7052-28-LH (Qty: 1) Pedal cover green, Part No. 7052-29-LH (Qty: 1) 3/16 X 1/2 Pop rivet (Qty: 2)	1	
M5 X 0.8-12 Button head screw	1	9
M5 Flat washer	1	0




- Rubber pedal becomes torn
- Metal lock pedal becomes severely deformed
- Pedal detaches
- Pedal is missing



Left Pedal Replacement Disassembly



Left Pedal Replacement Reassembly





Right Pedal Replacement Part No. 74348

Right Pedal Kit Bill of Material


Description	Quantity	
Right pedal assembly Lock pedal, Part No. 7052-16 (Qty: 1) Pedal cover red, Part No. 7052-28-RH (Qty: 1) Pedal cover green, Part No. 7052-29-RH (Qty: 1) 3/16 X 1/2 Pop rivet (Qty: 2)	1	
M5 X 0.8-12 Button head screw	1	0
M5 Flat washer	1	0




- Rubber pedal becomes torn
- Metal lock pedal becomes severely deformed
- Pedal detaches
- Pedal is missing



Right Pedal Replacement Disassembly



Right Pedal Replacement Reassembly





Top Cover Replacement Kit Part No. 74350

Top Cover Kit Bill of Material


Description	Quantity	
Top cover Top cover with handle, Part No. 7052-7 (Qty: 1) Blank mfg. label, Part No. 7052-60a (Qty: 1) 1/8 X 0.425 Aluminum pop rivet (Qty: 2)	1	
M6 X 0.8-20 Flat head screw	6	(B)
7052-24 Belt filler cover	1	
M5 X 0.8-16 Flat head screw	2	
M8 X 1.25 Hex lock nut	4	
M6 X 0.8-12 Button head screw	4	




- Large cracks
- Handle gone
- Regions of cover broken off




Top Cover Replacement Disassembly








Retractor Replacement Reassembly









Tire Grip Replacement Part No. 74353


Tire Grip Bill of Material

Description	Quantity	
Tire Grip, Part No. 7052-70	1	

- Ripped Missing



Tire Grip Replacement Disassembly



Tire Grip Replacement Reassembly

