James P. Grady
Assistant Vice President - Technical Services

ASSOCIATION OF AMERICAN RAILROADS

Wednesday, January 06, 2016

C-12550

Circular Letter

Subject:Solicitation of Comments: New Figure 40-A SHINGLES, PALLETIZED, MINIMUM 40 IN. × 40 IN., INCOMPLETE LAYER—RISERLESS CENTER A-FRAME FLATCARS – Section 5 AAR Open Top Loading Rules Manual (OTLR)

To:MEMBERS AND PRIVATE CAR OWNERS **File Number:LR 2.18.3**

The OTLRC requests comments from the industry regarding New Figure 40-A SHINGLES, PALLETIZED, MINIMUM 40 IN. × 40 IN., INCOMPLETE LAYER—RISERLESS CENTER A-FRAME FLATCARS – Section 5 AAR Open Top Loading Rules Manual (OTLR)

Therefore, in accordance with the requirements of AAR Rule 123, comments are herein solicited and should be sent with any additional attachments to: Mr. Travis Wolgram, Manager-AAR Loading Rules and Damage Prevention, TTCI, P.O. Box 11130, 55500 DOT Road, Pueblo CO 81001 or email to: travis_wolgram@aar.com. Comments may also be placed directly on the attached figure for clarity and submitted.

All comments received within 30 days from the date of this Circular Letter will be considered by the OTLR Committee prior to any action on the implementation of Figure 40-A in Section 5 of the Open Top Loading Rules Manual. The AAR has a long standing practice of seeking comments on changes and additions to rules or standards that may affect stakeholders. All are encouraged to voice their opinions with comments and questions to Mr. Travis Wolgram, Manager - AAR Loading Rules and Damage Prevention, TTCI, P.O. Box 11130, 55500 DOT Road, Pueblo CO 81001. Or email to travis_wolgram@aar.com or otlr@aar.com

Carriers are asked to ensure that copies of this circular letter are distributed to all concerned shippers and railroad personnel for their attention and guidance.

ON BEHALF OF THE OPEN TOP LOADING RULES COMMITTEE

Sincerely,
James P. Grady
Assistant Vice President - Technical Services
202-639-2141 202-639-2930 Email:jgrady@aar.org

Safety and Operations
Association of American Railroads
425 Third Street, SW, Suite 1000, Washington D.C. 20024

Attachments
section5p1.fig 40-a.20151214.pdf