

REFINISHING OF BRIDGE PLATES

Purpose: To provide the bridge plate running surface with an acceptable anti-

skid coating.

Scope: This procedure covers all Portable Bridge Plates produced in

accordance with AAR MSRP Spec. M-951 latest revision.

Procedure: Inspect bridge plate for damage and completeness.

Grit blast running surface to remove anti-skid finish.

Use a non-metallic blast media.

Remove all grit-blasting residue.

After running surface has dried, promptly apply Green Primer

Wash to a thickness of 0.5 mil max.

Apply Yellow Anti-Skid paint to running surface.

Note: Follow coating manufacturer's instruction regarding temperature of bridge plates, coating thickness and curing time.

Print "RF" and the date on the decal with permanent Marker.

Need Help: (708) 672-2300 or customerservice@hollandco.com

Effective Date: 6/4/2012

PLATE MAINTENANCE

INSTRUCTIONS

INSTRUCTIONS

PLATE MAINTENANCE